

Culvert Scope 2023

Culvert ID (RoadSegID-C#)	Inlet Parcel (Address)	Outlet Parcel (Address)	Culvert Dimensions (Inches)	Has Water Topped Road*	Repair Urgency (0-4)**	Comments/Condition/Other Info
Cam2-C1	4260	4260	16		4	inlet collapsed pipe, needs dirt removal
Cam4-C2	5241	4981	24	YES	3	inlet debris (25% restricted), inlet silted (10% restricted), lots of vegetation crowding outlet
Cam4-C3	4901	4920	18	YES	3	inlet needs reshaping and riprap (20% restricted), outlet silted (20% restricted)
Cam6-C2	4801	4710	24		3	outlet silted (30% restricted)
Cam8-C1	4601	4581	96	YES	3	lots of raspberries around inlet and outlet, large culvert, lots of graffiti (youth hangout?)
Cam11-C5	4281	4262	18		4	inlet restricted, outlet 1/2 filled with silt, reshape and riprap needed Hack --Porte
Cam11-C6	4220	4220	12		4	inlet clogged with debris and vegetation, culvert diameter is too small? Hafvenstein
Cam11-C8	2840 Strolling Hills	4072 Cameron	24		3	trees in ditch restricting flow, 1/3 filled with silt recommend pulling out all trees around culvert on Moulden property at 2840 Strolling Hills
Cam11-C8	1240	1225	12		4	intersection with Flying C Rd , inlet needs cleaning, outlet 1/2 silted, debris needs to be relocated
Fallen C2	4781		12	YES	3	outlet 50% silted
Fallen-C3	3048	3041	12		3	outlet 50% silted
FCC1-C1	4320	4360	12		3	intersection with Flying C Rd , inlet crushed 25% restricted and silted, inlet needs reshaping and riprap
** FlyC3-C2	4960 and 4881 grate	4955	12		4	inlet 100% plugged with debris, outlet 100% buried and at address 4881 Flying C Clear Inlet Grate to culvert –bid \$228
FlyC7-C3	4410	4411	32		4	inlet partially plugged, needs riprap outlet overgrown, needs cleaning
FlyC9-C2	outside CE	4091	?		4	culvert under CECSD road, outlet need cleaning, inaccessible behind fences
HiC3-C2	4880	4880	12		4	@Cam4, inlet crimped (50% restricted), outlet crimped and silted (50% restricted) SW Intersection Cameron Rd
Longview-C1	4721	4700	12		4	inlet silted (25% silted), outlet crushed and silted (75% restricted) Intersection Cameron Rd
Lar1-C2	3261	3280	12		4	outlet below grade, remove debris

Culvert Scope 2023

Culvert ID (RoadSegID-C#)	Inlet Parcel (Address)	Outlet Parcel (Address)	Culvert Dimensions (Inches)	Has Water Topped Road*	Repair Urgency (0-4)**	Comments/Condition/Other Info
Lar5-C3	2830	2801	20	YES	3	outlet side severely eroded, riprap
LL-E-C2	3770	3737	12		4	poplar tree growing at inlet (remove), reshape and riprap outlet, outlet silted (20% restricted)
Rancho-C1	4290	4301	12		4	inlet at very edge of road, inlet silted (50% restricted), outlet silted (80% restricted), outlet below grade (remove debris)
SH2-C1	3681	3681	18	YES	4	inlet silted (50% restricted), needs reshaping and riprap, outlet 24" below grade, standing water, create larger leach basin for outlet?
SH2-C2	3611	3640	?		4	Can't find inlet or see outlet, Peter says low place in ditch has culvert, completely buried? Locate and Clean Culvert
SH3-C4	3516	3516	18		4	heavy erosion in ditch leading to inlet (reshape and riprap), heavy erosion around outlet (riprap splash basin), labeled SH3-C1a in photos
SH5 C1	3134	3134				Pull out vegetation/tree stump crowding inlet & place Rip Rap Proft
Gold Spur C2	4903	4903			4	@cul-de-sac, inlet silted (80% restricted), inlet needs reshaping and riprap, outlet blocked by rocks (80% restricted, placed by residents?), outlet needs divertor and riprap splash basin Create 10 x 10 concrete slurry rip rap catch basin, clean culvert, expose outlet rip rap 20' and 70' rip rap leading to catch basin

* "YES" if water has recently overflowed the road, e.g. eroded downstream shoulder

** Judgement of urgency of repair; 0=> no repair needed, 4=> repair is urgently needed
