

## Cameron Road from Gate #2

Issue Number	Issue Type	Location	Length	Width	Shoulder backing FT	Grading FT	Priority (H,M,L)	Notes
1	Pot hole	4061 Flying C outside of Gate 2	20	20			H	outside of gate #2
2	Ditch reform	4061 Flying C outside of Gate 2	5	5			H	outside of gate #2
3	Shoulder backing/Grading	Cam1			245	979	H	
4	Shoulder backing/Grading	CAM2			550	3119	H	
5	Shoulder backing/Grading	CAM3			612	2446	H	
6	Shoulder backing/Grading	Cam4			917	2141	H	
7	Shoulder backing/Grading	CAM5				734	H	
8	Shoulder backing/Grading	CAM6			771	1431	H	
9	Shoulder backing/Grading	CAM 7				2569	H	
10	Shoulder backing/Grading	CAM8				2202	H	
11	Shoulder backing/Grading	CAM 9			61	550	H	
12	Shoulder backing/Grading	Cam 10				612	H	
13	Shoulder backing/Grading	Cam 11			3336	10,008	H	
14	Shoulder backing/Grading	CAM 12				1236	H	
15	Ditch asphalt	4601	5	2			H	

### NOTES

---



---



---

### TO DO

---



---



---





[illegible]

## NOTES

## TO DO

[illegible]

[illegible]

[illegible]

Dove Meadow

Issue Number		Issue Type	Location	Length	Width	Priority (H,M,L)	Notes
1	PH		C	3	3	H	2760 Dove meadow
Total				3	3	Area SF/ 9	

NOTES

TO DO



[illegible]

## NOTES

## TO DO

Deer Knoll Rd

Issue Number		Issue Type	Location	Length	Width	Priority (H,M,L)	Notes
1	DT		C	50	6	H	Intersection with cameron Rd
Total				50	6	Area SF/ 300	

NOTES

TO DO

[illegible]

## NOTES

## TO DO